



**Dominion**

# DAM INSPECTION CHECKLIST POSSUM POINT POWER STATION POND ABC

INSPECTION DATE: APRIL 6, 2016

WEATHER: 45°F & PARTLY CLOUDY

INSPECTED BY: K. ACRE

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	10:38 → SAND BAGS & RIBBON ARE IN PLACE, AND THERE IS NO STANDING WATER AGAINST SAND BAGS.
Erosion	N	N	SEVERAL BAGS ARE RIPPED.
Low Point, B dike*			
Flow	N	N	10:41 → SANDS BAGS ARE IN PLACE AND THERE IS NO STANDING WATER AGAINST SAND BAGS.
Erosion	N	N	A COUPLE SAND BAGS ARE RIPPED.
Outfall water surface El. (top of stoplogs to water)			10:51 → NO FLOW THROUGH WEIR, NO STANDING WATER AGAINST WEIR, AND WEIR APPEARS TO BE OK.

\* See figure below.

**Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.):** LOW POINT, C DIKE: 10:49 → SAND BAGS ARE IN PLACE AND THERE IS NO STANDING WATER AGAINST SAND BAGS, SEVERAL SAND BAGS ARE RIPPED. NO FLOW OR EROSION.

STANDING WATER ALONG TOP OF EMBANKMENT TO POUNDS (SEE FIGURE BELOW).

SOME WATER WITHIN POND LIMITS, TYPICAL OF ALL POUNDS.

